



354 Second St, Albany, NY 12206



ALBANY COUNTY
LAND BANK CORPORATION

Interior Photos – 354 Second St



First floor entranceway



Deteriorating Floor near front entrance



Gutted first floor to studs



More walls down to studs



ALBANY COUNTY
LAND BANK CORPORATION



Kitchen, deteriorating ceiling



Mold & subfloor rotting in front room



Spreading mold on doorframe, floors, and walls



**Rotting studs and deteriorating ceiling
beamboard**