

700 Smith Boulevard Existing Conditions Photo Log

September 28, 2021



Photo #1 –Existing Site From SE Looking NE (Crushed Millings Remediation Cap)



Photo #2 –Existing Site Looking NW (Crushed Millings Remediation Cap)



Photo #3 –Existing Site Looking North (Crushed Millings Remediation Cap & Existing Building Foundations)



Photo #4 –Existing Site From Center Looking NE (Crushed Millings Remediation Cap & Existing Building Foundations)



Photo #5 –Existing Site Along Raft St Looking East (Existing Building Foundations)



Photo #6 –Existing Site Along Raft St Looking West (Existing Building Foundations)



Photo #7 –Existing Perimeter Fence West Side



Photo #8 - Existing Hydrant/Water Line Center of Site




Photo #9 - Existing Hydrant/Water Line NW Corner