



Figure 1. Residence at 47 Holmes Dale seen from front sidewalk on Holmes Dale. Mature fruit trees that would screen the proposed fence visible to the right of house in side yard. Line of shrubbery along Cortland Street is visible on far right.



Figure 2. Line of shrubbery along Cortland Street with mature fruit trees and residence at 47 Holmes Dale visible behind. There is no sidewalk for pedestrians at this location. Front wall plane of the house is visible to the left of the photograph; real wall plane is obscured by fruit trees from this viewpoint.



Figure 3. Line of shrubbery continues along the side of the back yard of 47 Holmes Dale. Proposed fence would be located behind this line. Note the extensive vegetation.



Figure 4. Section between end of solid shrub line (to the left) and back of property (to the right). The proposed fence will be installed more or less along the back property line, screened by the extensive vegetation visible at the far right of the photo. Rear of residence at 47 Holmes Dale is visible.



Figure 5. View of shrub line along Cortland Street looking toward the street from inside the property. Rear wall plane of 47 Holmes Dale is visible at right. The proposed fence sections that extend from the corner of the house visible here out to the shrub line, and then along the shrub line from photo-right to photo-left, is the out-of-compliance section.



Figure 6. Extension of view presented in Figure 5 looking to the rear right corner of the property. The tree proposed for removal is NOT the large tree near photo-center, but rather the tree with a right-leaning trunk visible along the rear property line to the left of the large tree near photo-center.



Figure 7. View from rear of residence at 47 Holmes Dale looking toward rear property line. There is extensive vegetation that will remain between the proposed fence to be installed along the property line and the adjacent lot that will screen it almost entirely from view to residents at that property.



Figure 8. An extension of the view presented in Figure 7 looking towards and along the rear property line of 47 Holmes Dale. The rear left corner of the property is obscured by the apple tree seen in the photo. The large conifer shrubs that extend along the side property line are visible at the far left of the photo. The proposed fence will be installed on this side of these shrubs, therefore screening it entirely from the residents at the adjacent lot on this side.



Figure 9. View looking along shrub line towards rear of property at 47 Holmes Dale. Cortland Street is behind the shrub line visible at far right of photo. Note height of shrubs as compared to person taking photograph.