



52 Emmet St, Albany, NY 12204



Interior Photos – 52 Emmet St



Deteriorating stairs and exposed electric



Evidence of mold and water damage on second floor kitchen & bathroom



Evidence of water in ceiling causing bowing



Hole in the attic with evidence of damage from animals in ceiling